## National Transportation Safety Board Washington, DC 20594

## **Brief of Accident**

## Adopted 04/01/2003

| DEN02TA07 | 8 |
|-----------|---|
|-----------|---|

| File No. 12768   | 07/21/2002 Englewood, CO   |  | Aircraft Reg No. | N6271N                     | Time (Local): 15:37 MDT  |                      |
|--|----------------------------|--|------------------|----------------------------|--|----------------------|
| Engine Make/Mod  | s): None<br>on: Public Use | SD   | Crew<br>Pass     | Fatal<br>0<br>0            | Serious<br>0<br>0  | Minor/None<br>2<br>1 |
| Last Depart. Point: Destination: Same as Accident/Incident Location Airport Proximity: Airport Name: Centennial Runway Identification: Runway Length/Width (Ft): Runway Surface: Runway Surface Runway Surface Condition:  Canon City Same as Accident/Incident Location Centential Airport Centennial A5R A5P |                            | Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 10.00 SM Wind Dir/Speed: 050 / 012 Kts Temperature (°C): 29 Precip/Obscuration: None / None |                  |                            |  |                      |
| Pilot-in-Command A<br>Certificate(s)/Rating(s)<br>Commercial; Single-engine Lan<br>Instrument Ratings<br>Airplane  | ge: 63<br>d                |  | Т                | Total A<br>Las<br>Total Ma | me (Hours) All Aircraft: 10 st 90 Days: 27 ake/Model: 63 ment Time: 20 | 7<br>32              |

The wind was from 030 degrees at 9 knots, gusting to 15 knots, as the pilot made a simulated ILS approach to runway 35R. At decision height, the pilot transitioned to a visual approach and reduced power slightly to facilitate his descent and flared. The airplane ballooned and the pilot added a little power and maintained the attitude. The airplane landed hard, bounced, and came down on the nose wheel. He applied full power to reject the landing and the airplane began drifting to the left of the runway. The safety pilot took control of the airplane and returned it to the runway centerline. When the airplane touched down, it veered to the left, departed the runway, and skidded to a halt.

## Brief of Accident (Continued)

DEN02TA078

File No. 12768 07/21/2002 Englewood, CO Aircraft Reg No. N6271N Time (Local): 15:37 MDT

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) FLARE - IMPROPER - PILOT IN COMMAND

2. (F) REMEDIAL ACTION - IMPROPER - PILOT IN COMMAND

3. (F) MONITORING - INADEQUATE - COPILOT/SECOND PILOT

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. the pilot-in-command's improper flare resulting in a hard landing. Contributing factors were the pilot's improper remedial action, and the second pilot's inadequate monitoring of the flight.